



- Continuous process**
- ① Adsorption [75%]
 - ② Cooling
 - ③ Regenerating
 - ④ Combustion
 - ⑤ Hot water
 - ⑥ Hot air